

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	188794 2	(house or housing or case or casing or cover) with (half or part or portion or section)	US- PGPUB; USPAT; EPO; JPO; DERVENT
2	BRS	L2	987	(door bell or doorbell) and (transmitter or transmitting or transceiver or transceiving or receiver or receiving)	US- PGPUB; USPAT; EPO; JPO; DERVENT
3	BRS	L3	253	1 and 2	US- PGPUB; USPAT; EPO; JPO; DERVENT
4	BRS	L4	1237	antenna same (pushbutton or push button)	US- PGPUB; USPAT; EPO; JPO; DERVENT
5	BRS	L5	6	3 and L4	US- PGPUB; USPAT; EPO; JPO; DERVENT

	<b>Time Stamp</b>	<b>Comments</b>	<b>Error Definition</b>	<b>Errors</b>
<b>1</b>	<b>2005/01/09 18:11</b>			
<b>2</b>	<b>2005/01/09 18:12</b>			
<b>3</b>	<b>2005/01/09 18:12</b>			
<b>4</b>	<b>2005/01/09 18:12</b>			
<b>5</b>	<b>2005/01/09 18:15</b>			

	Type	L #	Hits	Search Text	DBs
6	IS&R	L6	1	("6775523").PN.	US- PGPUB; USPAT
7	BRS	L8	1384	door bell or doorbell and (transmitter or transmitting or transceiver or transceiving or receiver or receiving)	US- PGPUB; USPAT; EPO; JPO; DERWE NT
8	BRS	L9	14	L8 and L4	US- PGPUB; USPAT; EPO; JPO; DERWE NT
9	IS&R	L7	2453	((340/539.1) or (340/529.14) or (340/693.5) or (340/384.1) or (340/384.6)).CCLS.	US- PGPUB; USPAT

	<b>Time Stamp</b>	<b>Comments</b>	<b>Error Definition</b>	<b>Errors</b>
6	<b>2005/01/09 18:29</b>			
7	<b>2005/01/09 18:30</b>			
8	<b>2005/01/09 18:30</b>			
9	<b>2005/01/09 18:30</b>			